air barrier ING CLOSURE CONFERENCE RESTON **MAY 10-11**

To Scan or Not to Scan? Thermography is the Answer

Melissa I. Payne, BECxP, CxA+BE, CDT, Level II Building Science Thermographer

> Tremco CPG, Inc. Enclosure System Solutions



Air Barrier Association of America (ABAA) is a Registered Provider with The American Institute of Architects Continuing Education Systems. Credit earned on completion of this program will be reported to CES Records for AIA members. Certificates of Completion for non-AIA members are available on request.

This program is registered with the AIA/CES for continuing professional education. As such, it does not include content that may be deemed or construed to be an approval or endorsement by the AIA of any material of construction or any method or manner of handling, using, distributing, or dealing in any material or product.





Learning Objectives

- Gain knowledge on how to avoid costly rework due to common construction issues which can easily be visualized with infrared technology
- Gauge the importance of infrared technology and determine when building enclosure diagnostics and performance thermography testing solutions should be used during construction and to accompany other performance testing methods
- Become acquainted with the science behind infrared technology and interpret the difference between bulk moisture and air penetration
- Identify what a thermogram represents and differentiate basic thermal anomalies as they represent heat, air and moisture



AIA Continuing Education Provider

"Rework Costs — including labor, materials, equipment and subcontractors can run from 10% to 30% of a project's total contract amount."

MEIGSAPANE AGEA

Why is this Happening?

- Incomplete Design and Construction Documents
- Time Crunch Design and Construction
- Skilled Labor The Dying Craft
- Lack of Training for Trades
- Lack of Inspections Q/A & Q/C
- Lack of Coordination and Collaboration

RIGHT AFTER SOMEONE STOLE HER EXTERIOR CLADDING COLORING BOOK

MEIGERPANE AGEA

Why is this Happening?

- Incomplete Design and Construction Documents
- Time Crunch Design and Construction
- Skilled Labor The Dying Craft
- Lack of Training for Trades
- Lack of Inspections Q/A & Q/C
- Lack of Coordination and Collaboration

RIGHT AFTER SOMEONE STOLE HER EXTERIOR CLADDING COLORING BOOK



SUCCESS vs. FAILURE







What Is A "Test"



"A procedure intended to establish the quality, performance, or reliability of something, especially before it is taken into widespread use."

Oxford Dictionary







Thermal Imager Principle





Thermal Imager converts invisible infrared radiation into a visible image which we call thermograms

Electromagnetic Spectrum

- Defined by wavelengths
- Different wavelengths have different properties
- Our eyes see only visible light region
- Color is due to different wavelengths
- Infrared energy has no "color"







Resolution



Poor - 40x30, 80x60, 100x100, 120x120, 160x160, 320x240, 640x480... - Good



air barrier **abaa** association of america

FLIR One: 80x60

Testo T890: 640x480

Resolution





Low Resolution 140x140 pixel array 0.0196 MPixels Medium Resolution 320x240 pixel array 0.0768 MPixels Higher Resolution 640x480 pixel array 0.3072 MPixels



air barrier **abaa** association of america

Heat Flow Air Flow Moisture Flow

The 2nd Law of Thermodynamics

#1	#2	#3	#4
Moisture	Air	Heat	Vapor
Liquid Water	High to Low	Hot to Cold	High to Low
Control and	Control Passage of	Control Heat	Pressure
Disposal	air into and out of	Transfer	Diffusion –
	enclosure		Permeability

Drying Capacity

air barrier **abaa** association of america

Gravity acts down



air barrier



Non-traditional Means of Testing









Air Infiltration at Head of Curtain Wall





Air Infiltration on Exterior Wall in Return Air Plenum



Air Infiltration and Direct Transfer from Canopy





Air Infiltration and Direct Transfer from Canopy





Water Infiltration from Signage Anchoring on Exterior Wall



Thermal Capacitance

Mechanical duct temperature drop of 10°F



Thermal Capacitance

The Roof is Black!

No insulation, and no ventilation



Don't be Deceived



air barrier

america



Cool Spots due to poor air circulation

Don't be Deceived – LEED Gold?



air barrier **abaa** association of america



Air Infiltration from PTAC Unit

Don't be Deceived – LEED Gold?



air barrier **abaa** association of america



Direct Transfer – Energy Loss

Seeing past the Reflection





Non-standard Used to Narrow Down Point of Infiltration





Limitations












Commissioning Verification of Performance









Industry and Standards

ISO 6781-3:2015 Performance of buildings – Detection of heat, air and moisture irregularities in buildings by infrared methods

Part 3: Qualifications of equipment operators, data analysis and report writers.

air barrier **abaa** association of america (Results for residential and small buildings)



International Organization for Standardization

Industry and Standards



ASTM C1153 - 10(2015) 1

Standard Practice for Location of Wet Insulation in Roofing Systems Using Infrared Imaging

ASTM C1060-11a(2015)

air barrier **abaa** association of america Standard Practice For Thermographic Inspection Of Insulation Installations In Envelope Cavities Of Frame Buildings

Case Study conducted by: Miller Engineering, P.C.

Testing conducted for: Killian Construction & Robert Low



Every window and door on the project was to be tested and required to pass with no water infiltration criteria



Modified AAMA 501.2 Water Testing with No-Water Penetration/Infiltration Criteria Conducted



A leak occurred at the north jamb where a shim/anchor strap is located just below the window head.

MILLER ENGINEERING 3827 S. TIMBERCREEK AVE., SUITE A	AAM	A 501.2 FIE	WATER TI LD LOG	ESTING		
SPRINGFIELD, MD 65807 417-866-6664	Р	ROJECT IN	IFORMATION	N		-146 04
JOB #	4065	Date:	3/21/	/2018	Time:	12:45 a.m./ p.r
JOB NAME:			Primata	ira Residence		
ADDRESS:		317	D E. Farm Roa	ad 94, Spring	field, MO	
Miller Eng. Report Ref #: ME-B4	6.14W17.08					
TEST PERFORMED BY:	Cory V	Villiams, N	1elissa Payne		of Miller E	ngineering, P.C.
		TEST CO	NDITIONS			
AMBIENT AIR TEMP:	48 [°] F	:				
WEATHER CONDITIONS: Partly	cloudy					
TERTIEN CONDITIONSI TURA	FENE	ESTRATIO	N INFORMAT	ION		
LOCATION: B46.1	4/W17.08					
UNIT TYPE DOOR	- WOOD FRA	ME BRON		G - Radius wi	ndow abow	a
MANUFACTURER Albert	ini	, onon	APPROX	SIZE (L x W)		6'-6" x 11'-5"
				PRESSURE		30-35 PSI
		OBSER	ATIONS:			
lote: Observe and record any damage or deterions and record any damage or deterions	oration, missing o	r broken comp	oonents, miss adju	ustment of weath	erstrip or other	components, cleanliness of t
est specimen, out-or-square installations, missi	ng hasnings, etc.	ROOR	CAID	C000	EVCELLE	
Comments:	N OF UNIT:	POOK	FAIK	GOOD	EXCELLE	NT (NEW)
somments.						
AMPLING PROCEDURE: All app	licable door	and windo	w units are b	eing tested.	No samplin	g.
		TEST F	RESULTS			

A leak occurred at the north jamb where a shim/anchor strap is located just below the window head. Voids in the sealant are visible at this location.

eviations to test method

By signing this document, I hereby certify this test was performed in accordance with AAMA 501.2.

Cory Villi

Cory Williams, BE Tech, Level II Thermographer

Approved: Melissa Payne, BECxP, CxA+BE, CDT

Leak Point at every window identified at the stainless clips at both the head and jambs.



Leak Point confirmed with thermography where it could not be confirmed visually.



Unit failure at seals of operable windows.

98.8 80.1 FLIR ...

Installation failure jamb/sill flashing of windows.



Case Study conducted by: Miller Engineering, P.C.

Case Study conducted for: Killian Construction & CoxHealth



Thermal Performance of Curtain Wall System was studied and reviewed.

4' - 6" TO CL M 3' - 7 7/8" TO CL M 5 1/8" ALUMINUM CURTAIN WALL SYSTEM EF SECTION 1/2" BACKER ROD AND SEALANT-SILL PAN FLASHING TO MATCH CURTAIN WALL COLOR SET IN FULI BED OF SEALANT SLOPI COLD-FORMED METAL FRAMING- 6" MINERAL FIBER BOARD COLD-FORMED METAL 9' **INSULATION-3**" FRAMING- 6" ້ຄ VAPOR RETARDER FIRESTOPPING GYPSUM BOARD- 5/8' LEVEL 2 - W 👝 1301.54 🕓 T.O.R. 2 CONCRETE BEAM SECTION DETAIL- DETAIL C2 1 1/2" = 1'-0"

Shop Drawing Details



EFCO 5900; 2 1/2" X 6" W/ 2 3/4" DEEP COVERS

Predicting surface temperature and condensation of the building enclosure assembly is critical in understanding how components will maintain inside surface temps when thermal bridging in present.

air barrier **abaa** association of

america

Brick Spandrel Over Vision Head (R.H.=35%) Detail Color Image of Material Assignments wit Isotherm at Dew Point Temperature



UBJECT: Thermal Simulation

What is the anticipated surface temperature with heating design temperature of 3°F with a 15mph wind?

What about night sky radiation?

air barrier **abaa** association of

america

Brick Spandrel Over Vision Head (R.H.=35%) Detail Color Infrared Image with Temperatures at or Below the Dew Point and Lowest Interior Surface Temperature



SUBJECT: Thermal Simulation

air barrier

abaa

association of

america

According to Weather Underground (wunderground.com), weather conditions prior to and at the time of limited assessment were as follows:

CONDITIONS AT THE TIME OF INSPECTION

Outside ambient temperature	11°F – 25°F	Interior relative humidity	Varies
Interior ambient temperature	Varies	Sky conditions	Clear
Average wind velocity	4.6 mph	Wind chill temperature	2.9°F – 19°F

CONDITIONS 24-HOURS PRIOR & RECENT PRECIPITATION

Outside ambient temp. (min.)	11°F	Outside ambient temp. (max.)	40°F
Average wind velocity (wind chill)	7 mph	Average rainfall	0.00 in.

NICU Room 14 - Average Surface Temperatures on February 2, 2018 at 9:15am

	Average Average		
	Surface	Surface	
	Temperature	Temperature	ΔT Int/Ext
Location	Outside	Inside	Temperature
Top of sill member - approximately 1/2" from glass	22.5°F	47.6°F	25.1°F
Gasket - surface temperature of gasket material	22.6°F	44.8°F	22.2°F
Glass surface - approximately 1" from sill member	22.7°F	49.9°F	27.2°F

Note: Exterior ambient temperatures were documented at around 18°F at 8:52am and 22°F at 9:52am.

NICU Room 14 - Estimated Surface Temperatures on February 2, 2018 at 7:00am

		Ambient		Projected	Projected Interior
	Wind Chill at	Temperature	ΔT Int/Ext	Surface	Surface Temp with
Location	11°F and 7mph	Outside	Temperature	Temp Inside	Applied Wind Speed
Top of sill member - approximately 1/2" from glass	±0.2°F	±11°F	25.1°F	36.1°F	25.3°F
Gasket - surface temperature of gasket material	±0.2°F	±11°F	22.2°F	33.2°F	22.4°F
Glass surface - approximately 1" from sill member	±0.2°F	±11°F	27.2°F	38.2°F	27.4°F

Note: According to the design criteria used of: 3°F exterior temp, 72°F interior temp, wind velocity of 15 mph, relative humidity at 35% and dew point temperature of 42.9°F the projected surface temperatures of the frames above would result in surface condensation.

air barrier **abaa** association of america

Condensation Resistance Factor (CRF) was reviewed

AAMA 1503-98 – specifies a warm side temperature of 70°F and a cold side temperature of 0°F with a 15mph exterior wind





NICU Room #14: Image on left was taken upon arrival at 7:15am on 2/2/18. Image on the right was taken to document the reoccurrence of condensation within 30 minutes of drying glass and tube.





air barrier **abaa** association of america



NICU Room 14 – North Elevation



air barrier **abaa** association of america



NICU Room 14 – Baseline Reference

West light @ sill tube		
Measurements		
Sp1	46.4 °F	
Sp2	49.0 °F	
Sp3	49.0 °F	

air barrier **abaa** association of america



NICU Room 14 – Interior at Sill Tube

West side mid lite			
Measurements			
Sp1	50.8 °F		
Sp2	46.7 °F		
Sp3	46.6 °F		

air barrier **abaa** association of america



NICU Room 14 – Interior at Middle Tube

Note		
West side mid lite		
Measurements		
Sp1	61.1 °F	
Sp2	61.1 °F	





NICU Room 14 – Interior at Middle Lite

West outside of NICU14		
Measureme		
Bx1	Max	23.9 °F
	Min	22.3 °F
	Average	23.2 °F

air barrier **abaa** association of america



NICU Room 14 – Exterior at Sill Tube



air barrier **abaa** association of america



NICU Room 14 – Exterior Baseline





air barrier **abaa** association of america

North wall 5th floor looking north, structural steel temperatures are lower than frame temperatures. This image was taken at 10:00 am when exterior ambient temperatures were approximately 22°F. This image shows the frame sitting on the cold side of the exterior wall, directly onto the steel member. The spot surface temperatures are as follows: Spot1 - 46.7°F, Spot2 - 60.0°F, Spot3 – 51.0°F, Spot4 – 51.0 °F, Spot5 – 51.8°F, Spot6 – 59.8°F.

Exterior Chamber designed and installed







Exterior Chamber filled with dry ice


200 pounds of dry ice used in 21 hours



Interior Chamber climate controlled to mechanical system design.





Interior Chamber climate controlled to mechanical system design.







Thermocouples installed on interior and exterior at sill, lite, and wall on interior and exterior



Thermocouples installed on interior and exterior at sill, lite, and wall on interior and exterior



Thermocouples installed on interior and exterior at sill, lite, and wall on interior and exterior



Place	Date	Time	Value	Unit	Value	Unit	Value	Unit	Value	Unit	
1	5/30/2018	14:00:02	80	T1 KTemp	9999	T2 KTemp	9999	T3 KTemp	9999	T4 KTemp	F
2	5/30/2018	14:00:04	80	T1 KTemp	9999	T2 KTemp	9999	T3 KTemp	9999	T4 KTemp	F
3	5/30/2018	14:00:05	80	T1 KTemp	9999	T2 KTemp	9999	T3 KTemp	9999	T4 KTemp	F
4	5/30/2018	14:00:06	79.9	T1 KTemp	9999	T2 KTemp	9999	T3 KTemp	9999	T4 KTemp	F
5	5/30/2018	14:00:07	79.9	T1 KTemp	9999	T2 KTemp	9999	T3 KTemp	9999	T4 KTemp	F
1573	6/1/2018	11:05:18	37.5	T1 KTemp	37.2	T2 KTemp	28.6	T3 KTemp	36	T4 KTemp	F
1574	6/1/2018	11:06:18	37.7	T1 KTemp	37.2	T2 KTemp	28.7	T3 KTemp	36.1	T4 KTemp	F
1575	6/1/2018	11:07:18	37.9	T1 KTemp	37.4	T2 KTemp	28.6	T3 KTemp	36.1	T4 KTemp	F
1576	6/1/2018	11:08:18	37.9	T1 KTemp	37.5	T2 KTemp	28.4	T3 KTemp	36.3	T4 KTemp	F
1577	6/1/2018	11:09:18	38.1	T1 KTemp	37.7	T2 KTemp	31	T3 KTemp	36.6	T4 KTemp	F

air barrier **abaa** association of america

Exterior Thermocouple Readings – 21 hour acclimation

Date	Time	Value	Unit	Value	Unit	Value	Unit	Value	Unit
5/31/2018	9:58:58	71.7	T1 KTemp	71.1	T2 KTemp	72.5	T3 KTemp	75.5	T4 KTemp
5/31/2018	9:59:58	71.7	T1 KTemp	71.2	T2 KTemp	72.3	T3 KTemp	75.3	T4 KTemp
5/31/2018	10:00:58	71.7	T1 KTemp	71.2	T2 KTemp	72.3	T3 KTemp	75.2	T4 KTemp
5/31/2018	10:01:58	71.7	T1 KTemp	71.2	T2 KTemp	72.3	T3 KTemp	75.2	T4 KTemp
5/31/2018	10:02:58	71.7	T1 KTemp	71.4	T2 KTemp	72.3	T3 KTemp	75	T4 KTemp
6/1/2018	11:20:58	59.9	T1 KTemp	59.1	T2 KTemp	65.8	T3 KTemp	62.2	T4 KTemp
6/1/2018	11:21:58	60	T1 KTemp	59.4	T2 KTemp	65.8	T3 KTemp	62.1	T4 KTemp
6/1/2018	11:22:58	60.2	T1 KTemp	59.7	T2 KTemp	66	T3 KTemp	62.2	T4 KTemp
6/1/2018	11:23:58	60.4	T1 KTemp	59.7	T2 KTemp	66.3	T3 KTemp	62.2	T4 KTemp
6/1/2018	11:24:58	60.6	T1 KTemp	59.5	T2 KTemp	66.2	T3 KTemp	62	T4 KTemp
	Date 5/31/2018 5/31/2018 5/31/2018 5/31/2018 6/1/2018 6/1/2018 6/1/2018 6/1/2018 6/1/2018	DateTime5/31/20189:58:585/31/20189:59:585/31/201810:00:585/31/201810:01:586/1/201811:20:586/1/201811:21:586/1/201811:22:586/1/201811:23:586/1/201811:23:586/1/201811:24:58	DateTimeValue5/31/20189:58:5871.75/31/20189:59:5871.75/31/201810:00:5871.75/31/201810:02:5871.76/1/201811:20:5859.96/1/201811:22:5860.26/1/201811:23:5860.46/1/201811:23:5860.4	DateTimeValueUnit5/31/20189:58:5871.7T1 KTemp5/31/20189:59:5871.7T1 KTemp5/31/201810:00:5871.7T1 KTemp5/31/201810:02:5871.7T1 KTemp6/1/201811:20:5871.7T1 KTemp6/1/201811:21:5860.2T1 KTemp6/1/201811:23:5860.4T1 KTemp6/1/201811:24:5860.6T1 KTemp	DateTimeValueUnitValue5/31/20189:58:5871.7T1 KTemp71.15/31/20189:59:5871.7T1 KTemp71.25/31/201810:00:5871.7T1 KTemp71.25/31/201810:01:5871.7T1 KTemp71.25/31/201810:02:5871.7T1 KTemp71.46/1/201811:20:5859.9T1 KTemp59.16/1/201811:22:5860.2T1 KTemp59.76/1/201811:23:5860.4T1 KTemp59.76/1/201811:24:5860.6T1 KTemp59.5	DateTimeValueUnitValueUnit5/31/20189:58:5871.771 KTemp71.172 KTemp5/31/20189:59:5871.771 KTemp71.272 KTemp5/31/201810:00:5871.771 KTemp71.272 KTemp5/31/201810:01:5871.771 KTemp71.472 KTemp5/31/201810:02:5871.771 KTemp71.472 KTemp6/1/201811:20:5859.971 KTemp59.172 KTemp6/1/201811:21:5860.271 KTemp59.772 KTemp6/1/201811:23:5860.471 KTemp59.772 KTemp6/1/201811:24:5860.671 KTemp59.572 KTemp	DateTimeValueUnitValueUnitValue5/31/20189:58:5871.771 KTemp71.172 KTemp72.35/31/20189:59:5871.771 KTemp71.272 KTemp72.35/31/201810:00:5871.771 KTemp71.272 KTemp72.35/31/201810:01:5871.771 KTemp71.272 KTemp72.35/31/201810:02:5871.771 KTemp71.472 KTemp72.36/1/201811:20:5859.971 KTemp59.172 KTemp65.86/1/201811:21:5860.271 KTemp59.772 KTemp66.36/1/201811:23:5860.471 KTemp59.772 KTemp66.36/1/201811:24:5860.671 KTemp59.572 KTemp66.3	Date Time Value Unit Value Unit Value Unit 5/31/2018 9:58:58 71.7 71 KTemp 71.1 72 KTemp 72.5 73 KTemp 5/31/2018 9:59:58 71.7 71 KTemp 71.2 72 KTemp 72.3 73 KTemp 5/31/2018 10:00:58 71.7 71 KTemp 71.2 72 KTemp 72.3 73 KTemp 5/31/2018 10:01:58 71.7 71 KTemp 71.2 72 KTemp 72.3 73 KTemp 5/31/2018 10:02:58 71.7 71 KTemp 71.4 72 KTemp 72.3 73 KTemp 5/31/2018 10:02:58 71.7 71 KTemp 71.4 72 KTemp 72.3 73 KTemp 6/1/2018 11:20:58 59.9 71 KTemp 59.4 72 KTemp 65.8 73 KTemp 6/1/2018 11:22:58 60.2 71 KTemp 59.7 72 KTemp 66.3 73 KTemp 6/1/2018 11:24:58 60.6 71 KTemp 5	DateTimeValueUnitValueUnitValueUnitValue5/31/20189:58:5871.7T1 KTemp71.1T2 KTemp72.5T3 KTemp75.55/31/20189:59:5871.7T1 KTemp71.2T2 KTemp72.3T3 KTemp75.35/31/201810:00:5871.7T1 KTemp71.2T2 KTemp72.3T3 KTemp75.25/31/201810:01:5871.7T1 KTemp71.2T2 KTemp72.3T3 KTemp75.25/31/201810:02:5871.7T1 KTemp71.4T2 KTemp72.3T3 KTemp75.25/31/201811:20:5871.7T1 KTemp71.4T2 KTemp65.8T3 KTemp62.26/1/201811:22:5860.0T1 KTemp59.7T2 KTemp66.3T3 KTemp62.26/1/201811:23:5860.6T1 KTemp59.5T2 KTemp66.2T3 KTemp62.26/1/201811:24:5860.6T1 KTemp59.5T2 KTemp66.2T3 KTemp62.2

air barrier **aba** association of america

Interior Thermocouple Readings – 21 hour acclimation



FAILURE



Π

1000



air barrier **abaa** association of america

Introduction of Electric Heat strips were added to "warm" the window frame





Special Thanks to:



structural • forensic • building enclosure

For Case Study Thermograms





For the Knowledge



Melissa I. Payne BECxP, CxA+BE, CDT, Level II Building Science Thermographer

Manager Enclosure Solutions, Tremco CPG, Inc. M. 417.343.0094

mpayne@tremcoinc.com



Construction Products Group





ThankYou Sponsors!

